



BORGWARNER/KKK - TTR53039700432 - TURBO REPARADO BV43 HYUNDAI TUCSON 2.0

131583 28230-2F600 282302F600 28231-2F600 282312F600 53039700432 53039700435 53039800432
53039800435 53039880432 53039880435 53039900432 53039900435